

## D41HW 動作確認済みPC一覧

- 一覧にない機種は動作確認が未実施のものであり、正常動作しないという意味ではありません。
- 動作確認はパソコンメーカー出荷状態のパソコンで行っております。周辺機器を増設したり、設定変更を行っている場合には新たな設定が必要か、正常動作しない場合があります。
- 動作確認済みの機種について正常動作を確認しておりますが、お客様の環境において正常動作を保証するものではありません。また弊社で正常動作確認済みの機種でもパソコンの個体により正常動作しない可能性があります。

## ◆Acer

型番 (機種名)	OS
Aspire 3810T	Windows Vista Home Basic SP2 (32bit)
Aspire 4520	Windows Vista Home Basic SP2 (32bit)
Aspire 4530	Windows XP Home Edition SP3 (32bit)
Aspire 4930G	Windows Vista Home Premium SP2 (32bit)
Aspire 5320	Windows Vista Business SP2 (64bit)
Aspire 6920	Windows Vista Home Premium SP2 (32bit)
Aspire one	Windows Vista Ultimate SP2 (32bit)
Aspire 5530G	Windows Vista Business SP2 (32bit)

## ◆Apple

型番 (機種名)	OS
iMac (MB950J/A)	MacOS X 10.6.2
MacBook Air (MB003J/A)	MacOS X 10.5.4
MacBook Air (MB543J/A)	MacOS X 10.6.1
MacBook (MB062J/A)	MacOS X 10.6.4
MacBook (MB402J/A)	MacOS X 10.5.2
MacBook (MB404J/A)	MacOS X 10.5.8
MacBook (MB466J/A)	MacOS X 10.6
MacBook (MB467J/A)	MacOS X 10.5.7
MacBook (MC207J/A)	MacOS X 10.6.3
MacBook Pro (MC371J/A)	MacOS X 10.6.4
MacBook Pro (MA609J/A)	MacOS X 10.5.1
MacBook Pro (MA895J/A)	MacOS X 10.5
MacBook Pro (MB133J/A)	MacOS X 10.5.5
MacBook Pro (MB166J/A)	MacOS X 10.5.8
MacBook Pro (MB470J/A)	MacOS X 10.5.6

## ◆Asus

型番 (機種名)	OS
Eee PC 900-X	Windows XP Home Edition SP3 (32bit)
Eee PC1000H	Windows 7 Ultimate (32bit)
F5000R1	Windows XP Professional SP3 (32bit)
G2K	Windows Vista Home Premium SP2 (32bit)
Pro31F-AP101M	Windows XP Home Edition SP3 (32bit)
UL 20A	Windows 7 Home Premium (64bit)
UX50V	Windows Vista Home Basic SP2 (32bit)

## ◆Dell

型番 (機種名)	OS
Alienware M17	Windows 7 Home Premium (64bit)
Inspiron 13Z	Windows 7 Home Premium (64bit)
Inspiron 1420	Windows Vista Home Basic (32bit)
Latitude D630	Windows XP Professional SP3 (32bit)
Latitude D430	Windows XP Professional SP3 (32bit)
Latitude D520	Windows Vista Home Premium SP2 (32bit)
Latitude E4200	Windows Vista Home Basic SP2 (32bit)
Latitude E5400	Windows Vista Home Basic SP2 (32bit)
Latitude E6500	Windows Vista Ultimate SP2 (64bit)
Precision M2300	Windows Vista Business SP2 (32bit)
Studio XPS13	Windows Vista Home Premium SP2 (32bit)
Vostro 1200	Windows Vista Home Basic SP2 (32bit)
Vostro 1400	Windows XP Professional SP3 (32bit)
XPS M1330	Windows Vista Home Basic SP2 (32bit)
XPS M1530	Windows Vista Home Premium SP2 (32bit)

## ◆Fujitsu

型番 (機種名)	OS
A3130	Windows Vista Home Basic SP2 (32bit)
FMV-BIBLO LOOX M/E10	Windows 7 Starter (32bit)
FMV-BIBLO LOOX R/A70	Windows Vista Business (32bit)
FMV-BIBLO LOOX T50U/V	Windows Vista Home Basic (32bit)
FMV-BIBLO MG55U	Windows Vista Home Basic SP2 (32bit)
FMV-BIBLO MG/A75	Windows Vista Home Premium (32bit)
FMV-BIBLO MG/B75N	Windows Vista Home Premium SP1 (32bit)
FMV-BIBLO MG/D70	Windows Vista Home Premium SP2 (32bit)
FMV-BIBLO MT E50	Windows 7 Home Premium (32bit)
FMV-BIBLO NB55UD	Windows Vista Home Premium SP1 (32bit)
FMV-BIBLO NF40U/V	Windows Vista Home Basic SP2 (32bit)
FMV-BIBLO NX70W/D	Windows Vista Home Premium (32bit)
FMV-BIBLO R/E70	Windows 7 Professional (32bit)

## ◆Gateway

型番 (機種名)	OS
MT6452	Windows Vista Home Premium SP2 (32bit)

## ◆HITACHI

型番 (機種名)	OS
Prius Note PN34K5T	Windows Vista Home Basic SP2 (32bit)

## ◆HP

型番 (機種名)	OS
2230s	Windows XP Professional SP3 (32bit)
Compaq 2133 mini	Windows Vista Home Basic SP2 (32bit)
Compaq 2210b	Windows Vista Home Basic SP2 (32bit)
Compaq 6510b	Windows Vista Business SP2 (64bit)
Compaq 6515b	Windows Vista Home Basic SP2 (32bit)
Compaq 6535s	Windows Vista Business SP2 (32bit)
Compaq Presario V3500	Windows Vista Home Basic SP2 (32bit)
Compaq nc6220	Windows XP Professional SP3 (32bit)
G60	Windows Vista Home Premium SP2 (32bit)
Pavilion dm3-1010TX	Windows 7 Home Basic (32bit)
Pavilion dv5	Windows Vista Home Premium SP2 (32bit)
Pavilion dv9000	Windows Vista Home Premium SP2 (32bit)
Pavilion dv9206TX	Windows Vista Home Premium SP2 (32bit)
Pavilion dv9200/CT	Windows Vista Home Premium SP2 (32bit)
Pavilion dv9740	Windows Vista Home Premium SP2 (32bit)
Pavilion dv9852 eg	Windows Vista Home Premium SP2 (32bit)
Pavilion tx1000	Windows Vista Home Premium SP2 (32bit)

## ◆IBM

型番 (機種名)	OS
ThinkPad X31	Windows XP Professional SP3 (32bit)

## ◆KOHJINSHA

型番 (機種名)	OS
SA1F00	Windows XP Home Edition SP3 (32bit)
SX3KP06MA	Windows Vista Home Premium SP1 (32bit)

## ◆Lenovo

型番 (機種名)	OS
C200	Windows Vista Business SP2 (32bit)
G550	Windows 7 Professional (32bit)
IdeaPad S10	Windows XP Home Edition SP3 (32bit)
IdeaPad U350	Windows Vista Home Basic SP2 (32bit)
IdeaPad U450	Windows 7 Home Basic (32bit)
IdeaPad Y510	Windows Vista Home Premium SP2 (32bit)
ThinkPad R60e	Windows Vista Business SP2 (32bit)
ThinkPad SL400	Windows Vista Home Basic SP2 (32bit)
ThinkPad T400	Windows XP Professional SP3 (32bit)
ThinkPad T61	Windows XP Professional SP3 (32bit)
ThinkPad X200	Windows XP Professional SP3 (32bit)
ThinkPad X300	Windows XP Professional SP3 (32bit)
ThinkPad X60	Windows Vista Business SP2 (32bit)
ThinkPad Z61t	Windows XP Professional SP3 (32bit)
ThinkPad X100e	Windows 7 Professional (32bit)

## ◆MSI

型番 (機種名)	OS
U100	Windows XP Home Edition SP3 (32bit)
X340	Windows 7 Enterprise (32bit)

## ◆NEC

型番 (機種名)	OS
LaVie C LC900SG	Windows Vista Home Premium SP2 (32bit)
LaVie C LC950HJ	Windows Vista Ultimate (32bit)
LaVie G GL40UR5RC	Windows Vista Home Basic SP2 (32bit)
LaVie L LL550/M	Windows Vista Home Premium SP2 (32bit)
LaVie J LJ700/HH	Windows Vista Home Premium (32bit)
LaVie J LJ700/L	Windows Vista Home Premium SP2 (32bit)
LaVie L LM330/V	Windows 7 Home Premium (32bit)
LaVie L LL850WG	Windows 7 Home Premium (32bit)
LaVie L LL870/W	Windows 7 Home Premium (32bit)

## ◆ONKYO

型番 (機種名)	OS
R511A3	Windows 7 Home Premium (32bit)

## ◆Panasonic

型番 (機種名)	OS
CF-N8HYCADR	Windows 7 Professional (32bit)
CF-T5AW1PJR	Windows Vista Business SP2 (32bit)
CF-T5MW4AJR	Windows Vista Business (32bit)
CF-R8GW1AJR	Windows Vista Business SP2 (32bit)
CF-Y7AWDPJR	Windows Vista Business SP2 (32bit)
CF-N9JYCADR	Windows 7 Professional (32bit)
CF-S10AYADR	Windows 7 Professional (32bit)

## ◆SOTEC

型番 (機種名)	OS
C103B4	Windows XP Home Edition SP3 (32bit)
WinBook DN5020	Windows Vista Home Premium SP2 (32bit)

## ◆Sony

型番 (機種名)	OS
VGN-C51HA	Windows Vista Home Basic (32bit)
VGN-C61HB	Windows Vista Home Basic (32bit)
VGN-C51HB	Windows Vista Home Basic SP2 (32bit)
VGN-TZ73B	Windows Vista Ultimate SP2 (32bit)
VGN-BZAANS	Windows Vista Business SP1 (32bit)
VGN TT53FB	Windows 7 Home Premium (64bit)
VGN-FT53DB	Windows Vista Home Premium SP2 (32bit)
VGN-FW72JGB	Windows Vista Home Premium SP1 (64bit)
VGN-P72K/W	Windows 7 Home Premium (32bit)
VPCP119KJ/W	Windows 7 Home Premium (32bit)
VPCZ119FJ/S	Windows 7 Home Premium (64bit)

## ◆Sharp

型番 (機種名)	OS
PC-NJ70A	Windows Vista Home Basic SP2 (32bit)
PC-WE40S	Windows Vista Ultimate SP2 (64bit)
PC-WT70T	Windows Vista Home Premium SP1 (32bit)

## ◆Toshiba

型番 (機種名)	OS
dynabook AX/53C	Windows Vista Home Premium SP2 (32bit)
dynabook CX/45C	Windows Vista Home Premium SP2 (32bit)
dynabook SS RX1/S7A	Windows Vista Business SP2 (32bit)
dynabook SS SX/15A	Windows Vista Business SP2 (32bit)
dynabook TX/66E	Windows Vista Home Premium SP2 (32bit)
dynabook TX/67J2BLVD	Windows Vista Home Premium SP2 (64bit)
dynabook MX/33LRD	Windows 7 Home Premium (32bit)
dynabook Qosmio G30/97A	Windows Vista Home Premium SP2 (32bit)
dynabook Qosmio G40/97D	Windows Vista Home Premium SP2 (32bit)
NB100/HF PANB100HNUF	Windows Vista Home Basic SP1 (32bit)
PAUX23LNUWH	Windows 7 Starter (32bit)
Satellite P105	Windows Vista Home Premium SP2 (32bit)
Qosmio X300	Windows Vista Home Premium SP2 (32bit)